

RFQ fast tuning

Gennady Romanov May 1, 2008 Two fast motorized tuners, diameter of plungers is 45.24 mm, full stroke 25.4 mm.

The tuners affect both frequency and field distribution.




Tuning range for two tuners (synchronous movement) is **274 kHz**




Longitudinal distortion of electric field distribution in quadrants with plungers.

 $dE/E_aver*100\% = 17\%$ (initial 1,7%)




May 1, 2008

Longitudinal distortion of electric field distribution in quadrants without plungers.



Asimuthal asymmetry of electric field distribution in quadrants.



Conclusion

- The tuners are not effective very much.
- Because the field distortion they cause, they can be used during "warm up" only